



Ref: JUCED/ SS/SVV/01

Date-12/08/14

To Whom It May Concern

Sub: Stability certification of Proposed (G+ 2)School building at Vill+ Post- Purushottampur, Singur, Dist- Hooghly

Dear sir

Based on the study of the design and drawings(as stated below) as submitted to us this is to certify that the proposed school building Swami Vivekananda Vidyamandir is structurally safe as per relevant IS codes.

Thanking you

With regards

**For Deptt. of Construction Engg.,
JADAVPUR UNIVERSITY**

**Dr. Gokul Mondal
Associate Professor**

Dr. Gokul Mondal
Associate Professor
Dept. of Construction Engg.
Jadavpur University, Kolkata-98



DRAWING NOS :

a. ARCHITECTURAL

- 1) VVM/AR/ELEVATION/-01 DATED 27.03.13
- 2) VVM/AR/AIO DATED 27.03.13
- 3) VVM/AR/FP-01 DATED 27.03.13
- 4) VVM/AR/SECTION-01 DATED 27.03.13
- 5) VVM/AR/SITE-01 DATED 27.03.13
- 6) VVM/AR/ELEVATION-01 DATED 27.03.13

b. STRUCTURAL

- 1) C1/STR-17.05.13(SHEET 1 OF 4)
- 2) C1/STR-17.05.13(SHEET 2 OF 4)
- 3) C1/STR-17.05.13(SHEET 3 OF 4)
- 4) C1/STR-17.05.13(SHEET 4 OF 4)



**Principal
Swami Vivekananda Vidyamandir
Singur, Hooghly**

**Manager
Swami Vivekananda Vidyamandir
Purushottampur, Singur
Hooghly., W. B.**